

Report No.:	LS20230530	FACTORY PHOTO
Client:	N/A	
Supplier:	XXX	
Audited Factory:	XXX	
Contact Person:	XXX,	
Auditor:	xxx	
Audit Date:	20230530	
Factory Location:	XXX.	

GEN	GENERAL OVERVIEW			
	Fields	Score / 10	Weight / 5	Weighted Score
1	Factory Profile Legal Validity • Building Overview	8	5	40
2	Human Resource • Organization chart • Main contacts	7	4	28
3	Product and Market • Product • Export and Market	8	4	32
4	Production Facilities Production Workshops • Machinery List	7	4	28
5	Client Special Requirement	/	/	/
6	Support Documentation Short Videos • Photos • Documents	8	5	40
	Total:	38	22	168
Final S	Final Score: [Total weighted score / (10 * Total weight)]		76 /	/100

LEELINE
sourcing
Vese Trusted Sourcing Partner In China

Report No.: LS20230530

Report Date:

20230530

76/100

REN	REMARK		
Basi	Basic Remarks		
1.	Founded on XXX,XXX,XXX (hereinafter referred to as the supplier) was the owner XXX.		
2.	The business license provided by the supplier was consistent with the information on the government's website and actual finding, and the validity was confirmed.		
3.	The factory sold to both the domestic and overseas markets. 60 % was to overseas market, while 40 % was to the domestic markets		
4.	The factory can support for whole set solar energy products, include solar panel which is outsource.		
5.			
6.			

CONCLUSION

76/100

Daniel Lee

Approved by Daniel Lee, CEO of Report Reviewing

Auditor & Report Reviewer:



Auditor(s): Quick Chan Report Reviewer: Daniel

Leeline Sourcing Factory Audit Report

Report No.: LS20230530

Report Date:

20230530

76/100

Section 1 Factory Profile

1.1 Legal Validity		
Supplier Name:	xxx	
Audited factory's name:	xxx	
Relationship of Supplier & Audited factory:	□ Wholly Owned Shareholder □ Subcontractor □ Other	
Registration Number of Business license:	XXX	
Registered name of factory in local language:	XXX公司	
Year of established:	XXX	
Valid Date:	Long time	
Registered address:	xxx	
Actual add. conforms to registered add.?	Yes 🗆 No, actual add. is _	
Annual review by local authority (Industrial & Commercial Bureau)?	✓ Passed □ Expired □ Abnormal □ Other	
Last reviewed in year:	xxx	
Registered capital:	CNY XXX	
Name of legal representative:	xxx	
Client's interested product included in factory's business scope?	■ Yes □ No	
Company type:	✓ Manufactory □ Trading Company □ Combined	
Type of ownership:	Private Owner Public Company Joint Venture State-owned Foreign Capital	
Abnormal operation record at the government's website?	□ Yes ✓ No	

1.2 Basic Overview			
According to:	□ Land Certificate □ Real Estate Certificate □ Lease Agreement ■ Factory Officer Claimed + Actually Observed		
Total building size (□):	12,500 m2		
Number of buildings: 3		Office area (🛘):	2,000 m2



Report No.: LS20230530 Report Date:

20230530

Warehouse area (☐):

76/100

2,800 m2

	·	

Founded on XXX,XXX,XXX, XXX (hereinafter referred to as the supplier) was the owner XXX

5,000 m2


Factory land is leased

Production area (☐):


Score:

8

Section 2 Human Resource



2.2 Employee Details		
Department	Full-time employees	Part-time employees
GM	1	0
Admin. Dept.	20	0
Sales Dept.	72	0
Financial Dept.	11	0
Production Dept.	450	0
Engineering and R & D Dept.	60	0
Quality Dept.	20	0
Warehousing Dept.	32	0
Purchasing Dept.	10	0
In Total	676	0



Report Date: 20230530

	Name: XXX	
Sales Manager	E-mail: XXX	Less than 2 years
	Mobile: XXX	
Sales Representative	Name: XXX	
	E-mail: XXX	Less than 2 years
	Mobile: XXX	
4 - Sales Representative		



- The sales manager is XXX, has experience on mid-east, south Africa market Supplier mentioned total has 60 salesmen in this year 2023 for overseas

Section 3 Product and Market

3.1 Product		
Main products manufactured:	Inverter	
Other products manufactured:	Battery, UPS	
Client's interested product:	Inverter	
Main raw materials:	Metal, plastic	
Main production procedure:	Sewing, patch, assembly	
Available product certificates:	■ Licensed ■ Patents □ Awarded □ Brand certificate □ None ■ Other	

3.2 Export and Market			
With a valid export license?	✓ Yes □ No		
Export license code:	XXX		
The date of getting export license:	XXX		
The number of foreign trade salesman:	60		
Annual turnover of last 2 years(USD):	of last 2 2021: XXX million CNY 2022: XXX million CNY		
% of Export:	60% out of total turnover		
	 □ Domestic □ Europe □ North America □ South America □ Australia □ Japan □ South East Asia ☑ Middle East ☑ Africa □ Other 		
	Top 3 countries/ares	% of Total Business Volume	
Main markets:	Mid East	13%	
	Africa	11%	
	South America	10%	

Remark:

The factory sold to both the domestic and overseas markets. 60 % was to overseas market, while 40 % was to the domestic markets

Score

8

Leeline Sourcing Factory Audit Report LEELINE sourcing Report No.:

LS20230530 Report Date: 20230530 76/100

Section 4 Production Facilities

4.1 Production Workshops/ Lines		
Modernization of plant :	 □ Modern plant (Dust free or high automation plant) ■ Standard industrial plant □ Simple plant 	
Assembly line tidy and well organized?	□ Tidy and well organized ✓ Acceptable □ Chaos and poor management	
Production area well enlightened?	■ Yes □ No	
Production area Ventilated?	✓ Yes □ No	
Production area with cooling or heating facilities?	■ Yes □ No	

19 - Work shop



20 - Work shop




Leeline Sourcing Factory Audit Report

Report No.: LS20230530 Report Date: 20230530

21 - Work shop



22 - Work shop



23 - Work shop



24 - Work shop



25 - Work shop



26 - Work shop



Leeline Sourcing Factory Audit Report


Report No.: LS20230530 Report Date: 20230530 76/100

4.2 Machinery List			
Picture	Machine name	Amount	Use of state
E-FLOW B-FLOW	Wave-soldering	1	In useRepairingIdleOut of control
	Al machine	1	✓ In use□ Repairing□ Idle□ Out of control
	Automatic soldering machine	2	✓ In use□ Repairing□ Idle□ Out of control
	Wire-stripping machine	1	In useRepairingIdleOut of control



Report Date: Report No.: LS20230530 20230530

76/100



Remark:

- The main production lines include automatic wire marking machine.

Score:



Report No.: LS20230530

Report Date:

20230530

76/100

Section 5 Client's Special Requirement

Special requirement from client		
	Question:	
1.	Answer:	
2.	Question:	
	Answer:	
3.	Question:	
	Answer:	

Remark:

/

Score:

Photos:

4- business license



5- Warehouse




Report No.: LS20230530 Report Date: 20230530

76/100

Section 6 Support Documentation


6 - Workshop



7– Workshop



8 - Product test Room



9 – Test Area



Leeline Sourcing Factory Audit Report

Report No.: LS20230530 Report Date:

20230530

76/100





11 - Work shop



Leeline Sourcing Factory Audit Report

Report No.: LS20230530 Report Date: 20230530

76/100

12 - Product Kanban



13 - Work shop



14 - Work shop




15- Work shop



Leeline Sourcing Factory Audit Report

Report No.: LS20230530 Report Date: 20230530

16 – Showroom



17 – Showroom




Report No.: LS20230530 Report Date: 20230530

18 – Showroom

LEELINE sourcing



19 - Showroom



76/100

20 – Showroom



21- Showroom



22 – Showroom



23 – Showroom



Documents

Leeline Sourcing Factory Audit Report

Report No.: LS20230530 Report Date: 20230530

76/100





26 - ISO 14001

27 - ISO 9001






Leeline Sourcing Factory Audit Report

LS20230530 Report Date:

Report No.: 20230530





This is a region of another in manufacture of another in the control of the contr

76/100

29 - CE for inverter



30 - IEC 60896 for battery



Leelinesourcing.com

Leeline Sourcing Factory Audit Report


Report No.: LS20230530 Re

Report Date:

20230530

76/100





Documents

Leeline Sourcing Factory Audit Report


Report No.: LS20230530 Report Date: 20230530

76/100

33 – Office



34 – Office



35 – Model for ASG (without market limited)



36- Model for ASG (without market limited)

